



IWW Lock & Dam Status 17-Feb-22

Site	Status	Updates	Ice Thickness	Ice Coverage
Brandon Road	Normal Operations	Normal Operations. Ice Couplings Recommended	0"	0%
Dresden	Minor Impacts	Ice Couplings Required. Channel is clear of ice.	2"	5%
Marseilles	Minor Impacts	Ice Couplings Required. Upper and Lower 600' floating mooring bits on the island side of lock are operational. All other floating mooring bits are tied up.	2"	5%
Starved Rock	Minor Impacts	Ice Couplings Required. All floating mooring bits are tied up.	2"	10%
Peoria	Normal Operations	Wickets are down, pass is open. Heavy ice flows reported as of 1145 in response to the dam drop.	2"	100%
LaGrange	Minor Impacts	Wickets are down, pass is open.	.25"	5%

Status Key:	Normal Operations	Minor Impacts	Moderate Impacts	Significant Impacts	Lock Out of Operation
	No changes to everyday operations.	Ex: Ice Couplings, Floaters tied up.	Ex: Unable to pull cuts one or both directions, extended lockage times	Ex: Width and or length restrictions, drastically extended lockage times.	Lock is closed and cannot pass traffic.