



IWW Lock & Dam Status 1-Feb-23

Site	Status	Updates	Ice Thickness	Ice Coverage
Brandon Road	Normal Operations		0"	0%
Dresden	Minor Impacts	Ice couplings required .	1"	80%
Marseilles	Moderate Impacts	Ice couplings required . Helper boat needed for NB cuts. All floaters are now tied up.	1"	100%
Starved Rock	Moderate Impacts	Ice couplings required . Helper boat needed for NB cuts. Floaters are tied up.	1"	100%
Peoria	Moderate Impacts	Wickets are up, ice couplings required . Helper boat needed for NB cuts.	3"	95%
LaGrange	Moderate Impacts	Wickets are up, ice couplings required . Helper boat needed for NB cuts.	3"	80%

Status Key:	Normal Operations	Minor Impacts	Moderate Impacts	Significant Impacts	Lock Out of Operation
	No changes to everyday operations.	Ex: Ice Couplings, Floaters tied up.	Ex: Unable to pull cuts one or both directions, extended lockage times	Ex: Width and or length restrictions, drastically extended lockage times.	